Lex # 930 (AF) NEOIS/INIL 10/15/10

LIST OF CLASSIFIED STRUCTURES (LCS) SINGLE ENTRY REPORT

Identification-			1	10 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1 WWY: 27	
IDLCS: 06541		Struc	ران cture Number			
Structure Name 1 Structure Name 2 Structure Name 3	: HAYWARD WELL					
Park Alpha Code: MIMA Name: MINUTE MAN NATIONAL HISTORICAL PARK ORGCODE: 1820 County: MIDDLESEX State: MARGEONAL REGIONAL OFFICE: NORTH ATLANTIC						
Subunit ORGCODE: Alpha Code:	Name: County: I	MIDDLESEX		Sta	te: MA	
Number of U	TM's: 1		asting/North 14360 47017	ning 730		
Significance						
NR Status: EN - Significance: NO	MENTED		Date: 10/15/66			
NHL: NO Significance				Date: /	/	
ONE OF SEV. EXTANT WELL LEGENDARY INCIDENT BETW	L SITES ON FISKE FARM PR W. A BRITISH AND AN AMER EMY, MORTALLY WOUNDED TH	ICAN SOLDIER (INK	
——Historical Information————————————————————————————————————						
Period of Construction: HISTORIC						
Date: 1700-1775 (BU) Designer: Date: 1852-CA. (AL) Designer: Date: 1965-1966 (ST) Designer:NPS Date: - () Designer:				() () ()		
Functions, Uses, Materials, Impacts, and Condition						
Historic Functior IRRIGATION FACILI		RU	rrent Uses IN TERPRETATION	FACILITY		
Buildings—Materials—Structures—_						
Foundation: Framing:		Sub-structure: FIELDSTONE				
Walls: Roof: Other: Volume: Description			-structure:	STEEL		
SO-CALLED "HAYWARD WELL" IS CLOSED OFF WITH METAL GRILL; HAS STONE MARKERS. SECOND WELL W OF FISKE HOUSE SITE ALSO HAS A METAL GRILLE. THIRD WELL SITE APPARENTLY NOT STABILIZED OR MAINTAINED.						
Impact Level: I	-		VEGETATION EROSION			
Condition: F	FAIR					

LIST OF CLASSIFIED STRUCTURES (LCS) SINGLE ENTRY REPORT Continued

Park Structure Name Number IDLCS FISKE HILL WELLS 06541 MIMA 1-157-C -Management Information-Federal Owner: NPS Legal Interest: FEE Life: Exp. Date: Local Owner: Management Category: SHOULD BE PRES. & MAINT Management Date: 12/20/93 Management Agreement: NONE Agrmt. Exp. Date: Doc: Proposed Ultimate Treat: Date: Approved Ultimate Treat: NO TREATMENT Doc: NONE Date: Treatment Responsibilities Treatment Costs Interim Treatment: NPS \$0 Interim: Date: Ultimate Treatment: NPS Ultimate: \$0 Date: 12/92 Routine Maintenance: NPS Level of Estimate: Cyclic Maintenance: NPS Estimator: Approved Ultimate Treatment Completed: NO Management Text THERE HAS BEEN NO CONFIRMATION THAT THE WELL ADJACENT TO THE MONUMENT IS INDEED THE ACTUAL "HAYWARD WELL." Major Bibliographical References— Nat. Req.: 66000935 CSI: Nat. Cat: NO BRIDGES: HABS: DAMS: HAER: QTRS: CLI CRBIB Other 1. 1. HRS 1. 2. HS ASSESS 2. 2. HSR 3. 3. 3. CLR 4. 4. 5. Documentation Level: FAIR

Date of Report: 09/23/96

Logger: JIG

Date Entered/Updated: 02/16/94

page 2 of 2